	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	33234	flow adj meter		2006/11/18 18:48
2	BRS	L2	122	oval adj gear		2006/11/18 18:48
3	BRS	L3	31	1 same 2		2006/11/18 19:04
4	BRS	L4	755132	pump		2006/11/18 19:04
5	BRS	L5	520968 5	control\$4	1	2006/11/18 19:05
6	BRS	L6	4481	1 same 4 same 5		2006/11/18 19:06

	Туре	L#	Hits	Search Text	DBs	Time Stamp
7	BRS	L7	43270	set adj point	US- PGPUB; USPAT; FPRS; EPO; JPO	2006/11/18 19:06
8	BRS	L8	380171	feedback		2006/11/18 19:06
9	BRS	L9	194430	5 with (7 or 8)	US- PGPUB; USPAT; FPRS; EPO; JPO	2006/11/18 19:07
10	BRS	L10	886	6 and 9	US- PGPUB; USPAT; FPRS; EPO; JPO	2006/11/18 19:08
11	BRS	L11		meter\$3 or (positive adj displacement)		2006/11/18 19:09
12	BRS	L12	42801	11 with 4	US- PGPUB; USPAT; FPRS; EPO; JPO	2006/11/18 19:11

	Туре	L#	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	20997	positive adj displacement		2006/11/18 19:11
14	BRS	L14	354	1 with 13		2006/11/18 19:20
15	BRS	L15	41	10 and 12 and 14		2006/11/18 19:20